

MEDWAY PORTS
NOTICE TO MARINERS
(No. 34 of 2008)

**MEDWAY APPROACH CHANNEL
MEDWAY SECONDARY CHANNEL
AMENDMENT TO LIGHT CHARACTERISTICS**

NOTICE IS HEREBY GIVEN that with **immediate effect** the **light characteristics of the new Medway Secondary Channel navigation buoys** have been amended.

2. The following navigation buoys are affected:-

NAME	TYPE	POSITION	CHARACTERISTICS
2A	SPECIAL	51° 28.2304' N 00° 50.5212' E	Fl(2)Y.5s
4A	SPECIAL	51° 28.0120' N 00° 49.4121' E	Fl(2)Y.5s
6A	SPECIAL	51° 27.8777' N 00° 48.5753' E	Fl(2)Y.5s
8A	SPECIAL	51° 27.7020' N 00° 47.6851' E	Fl(2)Y.5s
10A	SPECIAL	51° 27.5561' N 00° 46.9233' E	Fl(2)Y.5s

3. The latest information on the amended Medway Secondary Channel navigation buoys light characteristics may be obtained from the Medway Navigation Service on VHF Channel 74, callsign "Medway VTS," or telephone (01795) 663025.
4. Admiralty Chart No. 3683 refers.
Medway Ports Notice to Mariners No. 32 of 2008 refers.

Captain S.M. Gobbi
HARBOUR MASTER

Medway Ports
Sheerness Docks
Sheerness
Kent
ME12 1RS

8th September 2008



Issued on behalf of Port of Sheerness Ltd
the Statutory Harbour Authority for the River Medway
Telephone calls, VHF radio traffic, CCTV and radar traffic images
may be recorded at the VTS Centre at Sheerness.