



PEEL PORTS MEDWAY

NOTICE TO MARINERS

(No. 43 of 2008)

**EAST SWALE
NORTH & SOUTH FERRY BUOYS
CHANGE OF CHARACTERISTICS**

NOTICE IS HEREBY GIVEN that with immediate effect the characteristics of the North Ferry and South Ferry navigation buoys in the East Swale have been amended.

2. The new characteristics are as follows:

North Ferry 51° 21.883' N 00° 46.524' E

GREEN conical buoy **Light Fl.G.2s**

South Ferry 51° 21.852' N 00° 46.474' E

RED can buoy **Light Fl.R.2s**

3. The latest information on the changes may be obtained from the Medway Navigation Service on VHF Channel 74, callsign "Medway VTS", or telephone (01795) 663025.
4. Admiralty Chart No. 2572 refers.

Captain S.M. Gobbi
HARBOUR MASTER

Peel Ports Medway
Sheerness Docks
Sheerness
Kent
ME12 1RS

24th December 2008